ATN Inspection Services, LLC

Propery Inspection Report



2346 Anystreet, Anytown, AR 79999 Inspection prepared for: John Client Date of Inspection: 2/1/2015 Time: 14:00 Age of Home: 8 Size: 1780 Weather: Overcast, 41 degrees

Inspector: Alton Darty
License #HI-1496
PO Box 531, Osceola, AR 72370
Phone: (870) 822-0124
Email: adarty@rittermail.com
www.arinspections.com



Not for distribution. This report and all descriptions, comments and photos are the intellectual property of ATN Inspection Services, LLC and may not be shared, reproduced or retransmitted without the express written consent of ATN Inspection Services, LLC. ATN Inspection Services, LLC grants only the named client use of this report and no other party should rely on any information contained therein.

INTRODUCTION

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your emailed report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFCI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non code, non cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk through inspection immediately before closing to check the condition of the property, using this report as a guide.

PURPOSE AND SCOPE

This Inspection Report is supplemental to the Property Disclosure Statement.

This document was prepared as a report of all visual defects noted at the time and date of the inspection. It is not necessarily an all inclusive summary, as additional testing or inspection information/processes and analysis may be pending. It is subject to all terms and conditions specified in the Inspection Agreement.

It should be noted that a standard pre-purchase inspection is a visual assessment of the condition of the structure at the time of inspection and is subject to day-to-day changes. The inspection and inspection report are offered as an opinion only, of items observed on the day of the inspection. Although every reasonable effort is made to discover and correctly interpret indications of previous or ongoing defects that may be present, it must be understood that no guarantee is expressed nor implied nor responsibility assumed by the inspector or inspection company for the actual condition of the building or property being examined.

This firm endeavors to perform all inspections in substantial compliance Standards of Practice set forth by the Arkansas Home Inspectors registration Board and the SOP can be viewed at www.ahib.org. The scope of the inspection is outlined in the Inspection Agreement, agreed to and signed by the Client. Our inspectors inspect the readily accessible and installed components and systems of a property as follows: This report contains observations of those systems and components that are, in the professional opinion of the inspector authoring this report, significantly deficient in the areas of safety or function. When systems or components designated for inspection in the Standards are present but are not inspected, the reason the item was not inspected may be reported as well.

This report summarizes our inspection conducted on this date at the above address.

EXCLUSIONS AND LIMITATIONS

The inspection is supplemental to the Property Disclosure Statement. It is the responsibility of the Client to obtain any and all disclosure forms relative to this real estate transaction. The client should understand that this report is the assessment of a Property Inspection Consultant, not a professional engineer, and that, despite all efforts, there is no way we can provide any guaranty that the foundation, structure, and structural elements of the unit are sound. We suggest that if the client is at all uncomfortable with this condition or our assessment, a professional engineer be consulted to independently evaluate the condition, prior to making a final purchase decision.

This inspection is limited to any structure, exterior, landscape, roof, plumbing, electrical, heating, foundation, bathrooms, kitchen, bedrooms, hallway, and attic sections of the structure as requested, where sections are clearly accessible, and where components are clearly visible. Inspection of these

components is limited, and is also affected by the conditions apparent at the time of the inspection, and which may, in the sole opinion of the inspector, be hazardous to examine for reasons of personal or property safety. This inspection will exclude insulation ratings, hazardous materials, retaining walls, hidden defects, buried tanks of any type, areas not accessible or viewable, and all items as described in the Inspection Agreement. As all buildings contain some level of mold, inspecting for the presence of mold on surfaces and in the air is not a part of the actual inspection, but is a value added service to help you, the client, minimize the risks and liabilities associated with Indoor Air Quality.

The Standards of Practice of the AHIB are applicable to all residential properties. They are not technically exhaustive and do not identify concealed conditions or latent defects. Inspectors are not required to determine the condition of any system or component that is not readily accessible; the remaining service life of any system or component; determination of correct sizing of any system or component; the strength, adequacy, effectiveness or efficiency of any system or component; causes of any condition or deficiency; methods, materials or cost of corrections; future conditions including but not limited to failure of systems and components; the suitability of the property for any specialized use; compliance with regulatory codes, regulations, laws or ordinances; the market value of the property or its marketability; the advisability of the purchase of the property; the presence of potentially hazardous plants or animals including but not limited to wood destroying organisms or diseases harmful to humans; mold; mildew; the presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water or air; the effectiveness of any system installed or methods utilized to control or remove suspected hazardous substances; the operating costs of any systems or components and the acoustical properties of any systems or components.

Inspectors are not required to operate any system or component that is shut down or otherwise inoperable; any system or component which does not respond to normal operating controls or any shut off valves or switches. Inspectors are not required to offer or perform any act or service contrary to law; offer or perform engineering services or work in any trade or professional service. We do not offer or provide warranties or guarantees of any kind or for any purpose. Inspectors are not required to inspect, evaluate, or comment on any and all underground items including, but not limited to, septic or underground storage tanks or other underground indications of their presence, whether abandoned or active; systems or components that are not installed; decorative items; systems or components that are in areas not entered in accordance with the Standards of Practice; detached structures; common elements or common areas in multi-unit housing, such as condominium properties or cooperative housing.

Inspectors are not required to enter into or onto any area or surface, or perform any procedure or operation which will, in the sole opinion of the inspector, likely be dangerous to the inspector or others or damage the property, its systems or components; nor are they required to move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice or debris or dismantle any system or component, or venture into confined spaces. Our inspectors are not required to enter crawlspaces or attics that are not readily accessible nor any area which has less than 36" clearance or a permanently installed walkway or which will, in the sole opinion of the inspector, likely to be dangerous, inaccessible, or partially inaccessible to the inspector or other persons, or where entry could possibly cause damage to the property or its systems or components. Inspector wants the Client to know that he is not a licensed Professional Engineer or Architect, and does not engage in the unlicensed practice of either discipline. Opinions contained herein are just that.

A WORD ABOUT RODENTS, VERMIN, AND PESTS

Vermin and other pests are part of the natural habitat, but they often invade buildings. Rats and mice have collapsible rib cages and can squeeze through even the tiniest crevices. And it is not uncommon for them to establish colonies within basements, crawlspaces, attics, closets, and even the space inside walls, where they can breed and become a health hazard. Therefore, it would be prudent to have an exterminator evaluate the structures to ensure that it is rodent proof, and to periodically monitor those areas that are not readily accessible.

A WORD ABOUT CONTRACTORS AND 20-20 HINDSIGHT

A common source of dissatisfaction with inspectors sometimes comes as a result of off the cuff comments made by contractors (made after the fact), which often differ from ours. Don't be surprised when someone says that something needed to be replaced when we said it needed to be repaired, replaced, upgraded, or monitored. Having something replaced may make more money for the contractor than just doing a repair. Contractors sometimes say, "I can't believe you had this building inspected and they didn't find this problem." There may be several reasons for these apparent oversights:

Conditions during inspection - It is difficult for clients to remember the circumstances in the subject property at the time of the inspection. Clients seldom remember that there was storage everywhere, making things inaccessible, or that the air conditioning could not be turned on because it was 60° outside. Contractors do not know what the circumstances were when the inspection was performed.

The wisdom of hindsight - When a problem occurs, it is very easy to have 20/20 hindsight. Anybody can say that the roof is leaking when it is raining outside and the roof is leaking. In the midst of a hot, dry, or windy condition, it is virtually impossible to determine if the roof will leak the next time it rains. Predicting problems is not an exact science and is not part of the inspection process. We are only documenting the condition of the property at the time of the inspection.

A destructive or invasive examination - The inspection process is non destructive, and is generally non-invasive. It is performed in this manner because, at the time we inspected the subject property, the Client did not own, rent, or lease it. A Client cannot authorize the disassembly or destruction of what does not belong to them. Now, if we spent half an hour under a sink, twisting valves and pulling on piping, or an hour disassembling a furnace, we may indeed find additional problems. Of course, we could possibly CAUSE some problems in the process. And, therein lies the quandary. We want to set your expectations as to what an inspection is, and what it not.

We are generalists - We are not acting as specialists in any specific trade. The heating and cooling contractor may indeed have more heating expertise than we do. This is because heating and cooling is all he's expected to know. Inspectors are expected to know heating and cooling, plumbing, electricity, foundations, carpentry, roofing, appliances, etc. That's why we're generalists. We're looking at the forest, not the individual trees.

Exterior

• You should consider rekeying all locks at exterior doors to insure that you control all the keys to the home. You should also consider reprogramming keypads and remotes for garage doors as a security precaution.



Exterior Door Condition

2. Storm doors

Good	Fair	Poor	N/A	S/H
1 1			X	
			<i>,</i> ,	

3. Wall Comments

Good	Fair	P001	IN/A	S/□	
					Met
X					Obs

Method: Conventional Stick Framing, Brick Observations:

• Recommend sealing all cracks and crevices to promote a tight building structure which prevents water, insects and rodents from entering structure



Damaged/missing receptacle cover near front entry

John Client	2346 Anystreet, Anytown, AR
4. Siding Comments	
Good Fair Poor N/A S/H	Materials: Brick Observations: • Functional • Recommend sealing all cracks and crevices to promote a tight building structure which prevents water,insects and rodents from entering structure • Gaps in mortar joint observed, recommend sealing to prevent cracks and or spalling
5. Trim Condition	
Good Fair Poor N/A S/H	Trim Materials: Metal, Vinyl Observations: • Deterioration noted to caulking around window or door trim. Recommend removing any loose material before application using a high quality silicone based caulk.
6. Window Conditions	
X Fair Poor N/A S/H	Window Types: Vinyl Observations: • Recommend annual inspection and caulking of any failed gaps/seams with a high quality grade caulk.
	 Damaged or missing screen/s noted at time of inspection. Recommend confirming that all screens are present.
	 One or more screens have damage/holes and are in need of repair.
7. Door Bell	
Good Fair Poor N/A S/H	Observations: • Operated • Damaged button
8. Hose Bibb Condition	on
X Poor N/A S/H	Valve type: Frost Proof Type Observations: • Appears Functional
9. Lighting Comments	
X Poor N/A S/H	Observations: • Appears Serviceable
10. Receptacle/Wiring	g Comments
X Fair Poor N/A S/H	Observations: • GFCI was tested and operated correctly. • Broken/Missing water proof cover noted at exterior outlet, repairs recommended for enhanced safety to occupants.

11. Chimney Condition

Good	Fair	Poor	N/A	S/H	
			Х		Locations: N/A


12. Brick/Stone



• Loose/deteriorated mortar noted, recommend repairs to prevent further deterioration to wall covering.

13. Vent Covers

Good	Fair	Poor	N/A	S/H
1 1				



Dryer vent loose at wall

Grounds

1. Driveway

X Materials: Concrete Observations:	Good	Fair	Poor	N/A	S/H	
X Observations:						Materials: Concrete
	Х					Observations:

Appears Serviceable



2. Sidewalks

Good	Fair	Poor	N/A	S/H
Χ				

Materials: Concrete Observations:

Appears Serviceable



3. Retaining Walls

Good	Fair	Poor	N/A	S/H	
					Locations: Front of Structure
			X		Locations: Front of Structure

4. Patio conditions

Good	Fair	Poor	N/A	S/H
Х				

Locations: Front of Structure Patio Materials: Brick, Concrete

Observations:

- appears serviceable
- Bricks are settled/displaced at perimeter of patio. Seal gaps to prevent water intrusion into the area.

John Client 5. Porch condition Poor Locations: Front of Structure Χ Materials: Concrete. Same as exterior walls Observations: Appears Serviceable 6. Deck/s Locations: N/A Χ 7. Stairs Fair Locations: N/A Χ 8. Landing Χ

10. Fence & Gates

9. Railings




N/A

Observations:

- Repairs needed to gates.
- Some loose boards noted.

11. Grading



Observations:

- Lot appears to be mostly flat with very limited slope for water drainage away from structure <FYI>
- Improper slope or low spot of grading near foundation noted. Recommend upgrading drainage to prevent water intrusion into structure.



Poor drainage. French drain, regrading or other repairs needed

12. Sprinkler System

Good	Fair	Poor	N/A	S/H
			Х	

Roof

As with **all** areas of the house, we recommend that you carefully examine the roof immediately prior to closing the deal. Note that walking on a roof voids some manufacturer's warranties. Adequate attic ventilation, solar / wind exposure, and organic debris all affect the life expectancy of a roof (see **www.gaf.com** for roof info). Always ask the seller about the age and history of the roof. On any home that is over 3 years old, experts recommend that you obtain a roof certification from an established local roofing company to determine its serviceability and the number of layers on the roof. We **certainly** recommend this for any roof over 5 years of age. Metal roofs in snow areas often do not have gutters and downspouts, as there is a concern that snow or ice cascading off the roof may tear gutters from the house. Likewise, be advised that such cascading may cause personal injury or even death. If this house has a metal roof, consult with qualified roofers or contractors regarding the advisability of installing a damming feature which may limit the size and amount of snow / ice sliding from the roof.

1. Number of layers

Good	Fair	Poor	N/A	S/H	
					Inspected By: View from ladder
X					Inspected By: View from ladder Number of Layers:
					 appears to be 1 laver

2. Roof Comments

Good	Fair	Poor	N/A	S/H	
					Method: Gable roof, Rafter Framing Materials: Asphalt
X					Materials: Asphalt



Boots at plumbing penetrations require more frequent repair/replacement than roof covering.

3. Low Slope Roof

Good	Fair	Poor	N/A	S/H
	Х			

Material: not fully visible for identification Observations:

• Recommend annual inspection of material/seams and removal of debris to extend the roofs useful lifespan.



Recommend annual inspection of material/seams and removal of debris to extend the roofs useful lifespan.

4. Shingle Condition

Good	Fair	Poor	N/A	S/H
V				
Х				

Shingle Type: Asphalt Composition Observations:

- Shingles appear to be 5-10 years into the 20-25 year average service lifespan for this type of roofing material.
- Shingles appear to be in serviceable condition at time of inspection. With PROPER maintenance roof should have a minimum of 5 years of service life left. Recommend annual review of shingles for signs of cracking, curling, missing shingles, loss of granules, moss growth and exposed fasteners. The normal life expectancy of asphalt shingles is 15-25 years. Shingles can wear out prematurely due to improper/lack of attic ventilation, recommend evaluation of ventilation performance by a qualified roofing contractor to assure that sufficient ventilation is present which will void most shingle manufacturers warranty due to improper installation practices.



Shingles appear to be in serviceable condition at time of inspection. With PROPER maintenance roof should have a minimum of 5 years of service life left. Recommend annual review of shingles for signs of cracking, curling, missing shingles, loss of granules, moss growth and exposed fasteners. The normal life expectancy of asphalt shingles is 15-25 years. Shingles can wear out prematurely due to improper/lack of attic ventilation, recommend evaluation of ventilation performance by a qualified roofing contractor to assure that sufficient ventilation is present which will void most shingle manufacturers warranty due to improper installation practices.

5. Soffit & Fascia Condition

Good	Fair	Poor	N/A	S/H	
Х					Materials: Metal, vinyl Observations:
					 Appears Serviceable

6. Gutters/Downspouts

Good	Fair	Poor	N/A	S/H
	Χ			
	/\			

Observations:

- Recommend addition of properly installed gutters and downspouts to enhance water drainage away from structure.
- Partially installed in areas
- Recommend extending downspouts to enhance drainage AWAY from structure.



Recommend extending downspouts to enhance drainage AWAY from structure.

ATN Inspection Services, LLC

7. Flashing

Good	Fair	Poor	N/A	S/H
Х				

Observations:

- Functional
- Not visible for review or inspection at time of inspection due to snow covering surface.

8. Skylights

Good	Fair	Poor	N/A	S/H
1 1			ΙXΙ	
			, ,	

9. Chimney

Good	Fair	Poor	N/A	S/H
			Х	

10. Spark Arrestor

Good	Fair	Poor	N/A	S/H
			Х	

11. Vent Caps

Good	Fair	Poor	N/A	S/H
	Х			

Observations:

- Homes ventilation appears to be insufficient, recommend evaluation by qualified roofing contractor for suggestions on upgrading to extend the shingle life expectancy.
- Turbine vent is damaged and is not functional.



Turbine vent is damaged

12. Roof Notes

Good	Fair	Poor	N/A	S/H

Observations:

• Satellite dish/antenna was observed mounted directly to shingles. This is considered poor practice as wind can cause fasteners to loosen which causes caulking failure. Moisture intrusion can lead to structural damage if left undetected due to lack of maintenance. Recommend relocating to a better suited location to prevent potential roof leaks in the future.



Satellite dish/antenna was observed mounted directly to shingles. This is considered poor practice as wind can cause fasteners to loosen which causes caulking failure. Moisture intrusion can lead to structural damage if left undetected due to lack of maintenance. Recommend relocating to a better suited location to prevent potential roof leaks in the future.

Attic

1. Access	
Observations: could not access all areas personal item prevent complete ir Access to attic area is limited and	
2. Chimney	
Good Fair Poor N/A S/H X	
3. Duct Work	
Observations: • functional • air leaking at plenum. Recommencase be properly sealed when serv	
4. Electrical	
X Poor N/A S/H Observations: • most not accessible due to insula	tion

5. Exhaust Vent

Good	Fair	Poor	N/A	S/H
		Х		

Observations:

Bathroom exhaust fan/s terminate into the attic, recommend proper venting to "exterior" air using an appropriate vent cap to prevent excess moisture in attic, which could lead to possible mold issues in the future if not corrected. Recommend review and repair by a Qualified Contractor.

• One or more exhaust fan ducts not visible for confirmation that bathroom exhaust fans terminate properly to the exterior, recommend further review to assure that there is no unwanted moisture terminating into the attic. It is not uncommon for bath fans to be improperly vented into the attic space which could potentially cause moisture buildup and possible indoor mold issues to arise.

6. Insulation Condition

Good	Fair	Poor	N/A	5/H
	V			
1 1	^			

Materials: loose fill, blown in insulation

Depth: 3-6 inches Observations:

- Functional
- One or more areas not accessible for inspection of insulation.




Attic Insulation Condition

7. Structure

Good	Fair	Poor	N/A	S/H	\sim 1
X					• F

Observations:

Functional



John Client	2346 Anystreet, Anytown, Al
4. Slab on Grade	
Observations: Slab is not visible due to construction type Slab is not visible at homes interior due to	e & style. o floor finishes installed.
5. Chimney Condition	
Good Fair Poor N/A S/H X	
6. Foundation Windows	
Good Fair Poor N/A S/H	
7. Door Comments	
Good Fair Poor N/A S/H X	
8. Floor Joist/Beam	
Good Fair Poor N/A S/H	
9. Insulation Condition	
Good Fair Poor N/A S/H X	
Crawlspace	
1. Crawlspace	
Good Fair Poor N/A S/H X	
2. Ventilation	
Good Fair Poor N/A S/H X	
3. Vent Screens	
Good Fair Poor N/A S/H X	
4. Access Panel	
Good Fair Poor N/A S/H X	
5. Foundation Walls	
Good Fair Poor N/A S/H X	

John Client	2346 Anystreet, Anytown, AF
6. Cripple Walls Good Fair Poor N/A S/H X	
7. Floor Joist/Beam Good Fair Poor N/A S/H X	
	Garage
1. Walls/Firewall	
Good Fair Poor N/A S/H	Observations: • Functional • Common dents and dings present
2. Anchor Bolts/Strap	S
Good Fair Poor N/A S/H	Observations: • could not access
3. Exterior Door	
Good Fair Poor N/A S/H	
4. Fire Door	
Good Fair Poor N/A S/H	Observations:
	Functional
5. Steps	
Good Fair Poor N/A S/H	Materials: Brick
6. Electrical	
Good Fair Poor N/A S/H	Observations: • Appears Functional
	Some areas not available due to personal belongings. Recommend removal of items to fully inspect wiring before the close of escrow.
7. GFCI	
Good Fair Poor N/A S/H	Observations: • Tested and operated correctly
8. 220 Volt	
Good Fair Poor N/A S/H	Observations: N/A

9. Flooring Condition

Good	Fair	Poor	N/A	S/H
Х				

Materials: Concrete Observations:

Functional

appears serviceable

10. Garage door condition

Good	Fair	Poor	N/A	S/H
Х				

Materials: Roll-up panel type number of doors: 1

number of doors: 1 Observations:

Functional



Functional

11. Garage Door Parts

Good	Fair	Poor	N/A	S/H
Х				

Observations:

- Functional
- Recommend routine lubrication to extend useable service expectancy.
- recommend adjustment
- Garage door is equipped with a key pad entry feature located at an exterior location. This feature was not able to test without the code. Recommend obtaining instruction manual for instructions on how to operate features and change/update code.

12. Garage Opener Status

Good	Fair	Poor	N/A	S/H
	Х			



Functional. Adjustment needed to closing force of operator

13. Garage Door's Reverse Status	
Observations:	
14. Roof Condition	
X Docation: same as the main structure Materials: asphalt shingles Observations: inspection was limited to viewing from ladder at eaves	
15. Rafters & Ceiling	
X Poor N/A S/H Observations: Functional	
16. Wash Basin	
Good Fair Poor N/A S/H X	
17. Storm/Screen Door	
Good Fair Poor N/A S/H X	
18. Vent Screens	
Good Fair Poor N/A S/H X	

Plumbing
Location: City Water Material: Not visible for identification Observations:
 Appears Functional at time of inspection. Not fully visible for inspection due to insulation/limited view of material.
PSI Observed: • 40 PSI
Materials: Cross Linked Polyethylene "PEX", Copper Observations: • Appears Functional • plumbing pipes not fully visible for inspection due to finished ceilings and walls
Fuel type: Natural Gas Location: Left side of structure Observations: • Gas shut-off valve location was shown to client for emergency purposes. • Inspection of gas line was possible due to limited access to all visible areas of gas line.
ipes
Materials: Poly Vinyl Chloride "PVC" Observations: • Appears Functional • Inspection of all areas of the drain pipes was not possible due to limited access/finshed walls and ceilings to check for defects such as, but not limited too:leaks, corrosion, improper workmanship, and damage. • Vent and Drain lines are not fully visible for inspection due to finished walls/ceiling preventing full view of plumbing.

5. Plumbing

Good	Fair	Poor	N/A	S/H	
					Materials: PE
					Observations:

• Recommend plumber to evaluate due to: unit is in need of cleaning, service.

6. Combustion

Good	Fair	Poor	N/A	S/H
	Х			

Observations:

- Functional
- rust flakes noted in burner chamber, this is a sign of deterioration to water heater from continuous heating and cooling. Recommend monitor and replace before tank failure which could result in water damage to structure/personnal belongings.

7. Venting

Good	Fair	Poor	N/A	S/H
	Х			

Observations:

- Functional
- Vent pipe appears to lacks "minimum" 1 inch clearance from combustible materials, recommend review and repair by qualified contractor.



Flue pipe is to close to HVAC duct

Electrical

1. Cable Feeds

Good	Fair	Poor	N/A	S/H
Х				

Service Type:

• Underground service conductors noted, not visible for inspection.

2. Main Amp Capacity

Good	Fair	Poor	N/A	S/H
Х				

Main Amp: 200 amp

3. Breakers in Off position
X Pair Poor N/A S/H Observations: 0
4. Electrical Panel
Location: Garage Sub Panel Location: none located Observations: • Main shut off switch location is noted for future reference. Home owners should have this information in the event of an
 emergency. Circuits do not appear to be properly/completely labeled at dead front cover, recommend identifying and labeling ALL circuits for enhanced safety to occupants. The main disconnect breaker is especially important to locate quickly in case of an emergency.
2015/08/05
Main shut off switch location is noted for future reference. Home owners should have this information in the event of an emergency.
5. Breakers X Panel Brand: Cutler Hammer Observations: • Functional
6. Fuses Good Fair Poor N/A S/H X
7. Conductor Comments Sood Fair Poor N/A S/H Wiring Method: Non metallic sheathed copper wiring Observations: • Functional



Label breakers

Security System

	Good	- Fair	Poor	N/A	S/H	
- [Observations: Security systems are not inspected as part of a nome
				I I	I I	esservations. Cocurry cyclomic are more more as part or a norm
				I I	I I	Observations: Security systems are not inspected as part of a home inspection.
		$\overline{}$		$\overline{}$	$\overline{}$	mapconom.

Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person. It is recommended that the HVAC equipment be cleaned, serviced and inspected at least once each year.

1. Heater Condition

Good	i aii	1 001	1 1/ /~1	0/11
				1
				1
				1
				1
$\overline{}$				

Location/s: Attic

Heat Type/s: Gas, Conventional forced air

Observations:

- Not operated due to outdoor temperatures.
- Unit does not appear to have been serviced annually per manufacturers instructions. Recommend having unit serviced annually to maintain efficiency and longevity of unit



HVAC equipment should be serviced at least once each year



Return air grilles in all bedrooms. Change filters each 30 days

Return all grilles in all bedrooms. Change litters each 30 days
6. Burners
Observations: • The inspector is not equipped to thoroughly inspect heat exchangers for evidence of cracks or holes, as this can only be done by dismantling the unit or other technical procedures. Some funaces are designed in such a way that inspection is almost impossible.
7. Venting
Good Fair Poor N/A S/H Observations: • Functional
8. Air Supply
X Poor N/A S/H Observations: • Functional
9. Registers
X Pair Poor N/A S/H Observations: • Functional
10. Refrigerant Lines
Good Fair Poor N/A S/H Observations: • Functional
11. AC Compress Condition
Type: Electric Location: Exterior Left Observations: • Operated



12. Condensate Pump
Good Fair Poor N/A S/H X
13. Condensate Line
Good Fair Poor N/A S/H
14. A/C Power
X Poor N/A S/H Materials: 240 vac Observations: Functional
15. Thermostats
X Poor N/A S/H Observations: • Functional
16. Radiators
Good Fair Poor N/A S/H X
17. Ductwork
Observations: Recommend sealing all gaps, cracks and holes in the HVAC duct system for increased efficiency and lower energy bills.



Heat/AC Ductwork

18. Heating Notes





Furnace manufactured in 2008

19. Humidifier notes



Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

John Chefit	2546 Arrystreet, Arrytown, A
1. Window Condition	
Good Fair Poor N/A S/H	Type/s: Vinyl single hung Observations: • Functional • Some windows were blocked by window treatments/personal items which prevented full review and operation of all windows. Recommend performing a walk thru inspection before close of escrow to confirm that all windows are operational and without defects or damage. • Missing screen/s at one or more windows.
2. Wall Condition	
Good Fair Poor N/A S/H	Materials: drywall Observations: • Common nail holes and patched areas noted as one or more locations.
3. Ceiling Condition	
Good Fair Poor N/A S/H	Materials: Drywall Observations: • Poor finishing details noted on seams at ceilings in some areas.
1 Doors	3
4. Doors Good Fair Poor N/A S/H X	Observations: • Functional
5. Ceiling Fans	
Good Fair Poor N/A S/H	Observations: • Operated
6. Electrical	
Good Fair Poor N/A S/H	Observations: • Functional
7. Closets	
Good Fair Poor N/A S/H	Observations: • Functional
8. Fireplace	
Good Fair Poor N/A S/H	Location/s: Living Room Type: Prefabricated, Gas Log Observations: • Appears Functional • Gas burning only <fyi></fyi>
9. Floor Condition	
X Fair Poor N/A S/H	Materials: multiple materials used Observations: • Appear Serviceable

John Client	2346 Anystreet, Anytown, AF
10. Sliding Doors	
Good Fair Poor N/A S/H X	
11. Screen Doors Good Fair Poor N/A S/H	
Good Fair Poor N/A S/H X	
12. Smoke Detectors Good Fair Poor N/A S/H C	
Observations: output fair Poor N/A S/H Observations: output output fair Poor N/A S/H Observations: output output fair Poor N/A S/H Observations: output output output fair Poor N/A S/H Observations: output out	<u> </u>
13. Stairs & Handrails	
Observations: Current building standards require that the wall to prevent loose clothing or a purse get caught and potentially present a safety review and repairs by a Qualified Contractor	e strap for example to hazard. Recommend
14. Bar	
Good Fair Poor N/A S/H Observations: • none	
15. Cabinets	
Observations: worn hardware loose hinges drawers difficult to slide	
16. Window-Wall AC/ Heat	
Good Fair Poor N/A S/H X	
Kitchen	
The kitchen is used for food preparation and often for entertainment. Kitchen, dishwasher, sink and other appliances. When possible kitchen applianction. Burners are turned on, dishwasher operated, disposal turned or operated, etc. Testing is only of operation and I cannot determine the efficalibration of equipment and so forth. Often older appliances function but energy efficiency, convenience and features of more modern equipment. equipment may also require a high level of maintenance for continued operation.	oliances are tested for n, range elements &ovens ciency of operation, the may not operate with the Older appliances and
1. Cabinets Good Fair Poor N/A S/H C	
Observations: otalian otalian	sonal belongings.
2. Ceiling Condition	
X Poor N/A S/H Materials: drywall	
Day 00 of 40	

ohn Client	2346 Anystreet, Anytow
3. Counters Good Fair Poor N/A S/H X	Observations: • Functional • some not visible due to personal items
4. Dishwasher	
Good Fair Poor N/A S/H	Observations: • Operated at time of inspection.
	2015/06/05 Kitchen Dishwasher
5. Doors	
Good Fair Poor N/A S/H	Observations: • functional
6. Electrical	
Good Fair Poor N/A S/H	Observations: • Functional
7. GFCI	
Good Fair Poor N/A S/H	Observations: • GFCI tested and functioned properly
8. Floor Condition	
Good Fair Poor N/A S/H	Materials: Tile
9. Garbage Disposal	

10. Microwave

Observations:

- Functional
- Operated at time of inspection.

Χ

11. Cook top condition

Good	Fair	Poor	N/A	S/H
Χ				

Observations:

- Operated at time of inspection.
- electric

12. Oven & Range

Good	_ Fair	Poor	N/A	S/H
1 1			1 1	1
1 1			1 1	1
1 1			1 1	1

Observations:

- Functional at time of inspection
- Electric
- No anti tip bracket installed on range.



Anti tip bracket needed at range

13. Plumbing

Good	Fair	Poor	N/A	S/H

Observations:

• Personal belongings prevented inspection of much of the plumbing areas under sink. Recommend review of plumbing pipes for areas of damage or leaks before the close of escrow.



Kitchen Plumbing

John Client	2346 Anystree	et, Anytown, AF
14. Sinks		
X Poor N/A S/H Obser	vations: Functional	
15. Vent Condition		
X Obser	ials: self filtering with fan vations: erated	
16. Wall Condition		
Good Fair Poor N/A S/H Materi	ials: drywall	
	Bathrooms	
Because of all the plumbing i air and leaks can cause milde inspection will identify as mar problems within the walls or underneath. Ventilation homes should have either an new construction standards hand mechanical ventilation (a of the structure and not into the standards). In larger baths a sable to determine the CFM (construction of the CFM)	any features from jacuzzi tubs and showers to toilets and bidenvolved it is an important area of the house to look over. Morew, wallpaper and paint to peel, and other problems. Our hony issues as possible but some problems may be undetectal under the flooring, tubs, and shower pans. Note that floor fixing space and construction style or insulation may observed in it is an important issue with bathrooms and all bathrooms in a operable window or a properly installed and operational extrave changed to require both natural ventilation (an operable an exhaust fan). All exhaust fans are required to terminate at the attic space (manufacturers installation instructions and manufacturers installation instructions and manufacturers in the any fans installed and will shave sufficient capacity to ventilate the area.	bisture in the me ble due to nishes existing haust fan. In e window) the exterior hodern ill not be
	ion/s: Master Bathroom, Main Floor Bathroom	
2. Wall Condition		
• wall to the wallp	ials: drywall vations: I paper is not recommended to be installed in bathro e potentially high moisture levels. The glue used to a aper is cellulose based and is the perfect food for u growth.	apply the
	se visit www.toxic-black-mold-info.com/findmold.htm rther information on mold.	1
3. Ceiling Condition		
X Poor N/A S/H Materi	ials: drywall	
4. Floor Condition		
X Obser	ials: Tile vations: pear Serviceable	

John Client	2346 Anystreet, Anytown, Al
	Observations: • Appear Serviceable • Need door stops at all interior doors. Damage to walls will result if there is not a doorstop or if doorstop in installed improperly.
7. Counters	Observations: • Functional
X	Observations: • Functional • Normal Wear
Good Fair Poor N/A S/H	
	Observations: • GFCI tested and functioned properly
	Observations: • Functional • Vent does not terminate to exterior air, repairs needed to prevent indoor moisture issues.
11. Heating Good Fair Poor N/A S/H X 12. Toilets	Observations: central unit, did not operate
Good Fair Poor N/A S/H	Observations: • Functioned properly at time of inspection • Toilet loose at floor, recommend wax ring replacement and proper fastening to closet flange drain by a qualified plumber. Water damage can occur due to toilet movement causing damage to the wax ring which allows waste water leakage.
13. Sinks	
Good Fair Poor N/A S/H	Observations: • Functional
	Observations: • Functional

John Client	2346 Anystreet, Anytown, Al
15. Showers Good Fair Poor N/A S/H X	Observations: • Functional. Light above tub in hall bath has a loose trim ring. Trim is not properly fitted and is not flush with ceiling.
16. Shower Walls Good Fair Poor N/A S/H X	
17. Bath Tubs Good Fair Poor N/A S/H X	
18. Whirlpool commer	nts
Good Fair Poor N/A S/H	Observations: • Visual observation did not verify that motor is GFCI protected, recommend upgrading for enhanced safety to occupants. • No access panel located for maintenance of pump and plumbing. <fyi></fyi>
19. Window Condition	
Good Fair Poor N/A S/H	Materials: stationary
	Bedrooms
walls, ceilings and floor and normal operation. inspector will not move fault circuit interrupter force at the time of co	ection in the bedrooms is the structural system. This means that all accessible ors will be inspected. Doors and windows will also be investigated for damage Personal items in the bedroom may prevent all areas to be inspected as the e personal items. If the home is of recent construction (1999 or later) AFCI (arc protected circuits should be present in the home. While local standards in instruction may not have required AFCI protected at the time of construction as consideration to installing this feature as a safety upgrade.
1. Locations	
	main floor #1, main floor #2, Master
2. Doors	
Good Fair Poor N/A S/H	Observations: • Functional • Door stops needed.
3. Wall Condition	
Good Fair Poor N/A S/H	Materials: • drywall Observations: • some areas not accessible due to personal items

John Chent	Z346 ANYSITEEL, ANYIOWN, 7
4. Floor Condition	
Good Fair Poor N/A S/H X	Materials: • carpet Observations: • Appear Serviceable
5. Ceiling Condition	
Good Fair Poor N/A S/H	Materials: • drywall • Observations: • patched areas. Master bedroom ceiling has poor finishing of seams.
6. Window Condition	
Good Fair Poor N/A S/H	Material and Type: vinyl Observations: • functional
7. Closets	
Good Fair Poor N/A S/H	Observations: • functional • limited inspection due to personal belongings
8. Electric	
Good Fair Poor N/A S/H	Observations: • some outlets not accessible due to personal belongings and furniture
9. Arc Fault Circuit In	terupters
Good Fair Poor N/A S/H	Observations: • Functional • AFCI breakers are not tested in occupied homes. You should test the AFCI breakers at least once each month to assure proper operation.
10. Smoke Detectors	
Good Fair Poor N/A S/H	Observations: • alarm system present not tested
11. Ceiling Fans	
Good Fair Poor N/A S/H	
12. Fireplace	
Good Fair Poor N/A S/H	
13. Window-Wall AC/	Heat
Good Fair Poor N/A S/H	Observations: none

John Client	2346 Anystreet,	Anytown, A
14 Caroon Doors		
14. Screen Doors Good Fair Poor N/A S/H Oh o matical street in the stre		
Observations: • none		
15. Cabinets		
Good Fair Poor N/A S/H Observations: • none		
16. Bar		
Good Fair Poor N/A S/H Observations: • none		
17. Security Bars		
Good Fair Poor N/A S/H Observations: none		
Laundry		
1. Locations		
Location: Laundry Room		
2. Cabinets		
Observations: loose hinges drawers difficult to slide		
3. Counters		
X Door N/A S/H Observations: • Functional		
4. Ceiling Condition		
X Poor N/A S/H Materials: drywall		
5. Dryer Vent		
Good Fair Poor N/A S/H Observations: • Routine cleaning of vent termination is rerisk of lint buildup posing a fire hazard. • loose exterior cover	commended to p	orevent
6. Electrical		
X Door N/A S/H Observations: • Electric dryer hookup present. <fyi></fyi>		
7. GFCI		
Good Fair Poor N/A S/H Observations: • GFCI recommended in all potential wet Ice	ocations	

8. Exhaust Fan
Good Fair Poor N/A S/H Observations: • none
9. Doors
X Door Poor N/A S/H Observations: • functional
10. Floor Condition
X Poor N/A S/H Materials: tile
11. Gas Valves
Good Fair Poor N/A S/H Observations: • none
12. Plumbing
Observations: • Manufactures recommend replacement of washing machine hoses every 5 years to reduce the chances of possible line rupture which causes hundreds of thousands of dollars in water damage every year. Recommend replacing lines with steel braided lines as this type is designed to provide added rupture resistance
13. Wall Condition
X Materials: drywall Observations: • some areas n/a personal items
44 Week Design

14. Wash Basin

X Doservations:



Laundry Wash Basin

Report Summary

Kitchen	
Page 32 Item: 12 Oven & Range	No anti tip bracket installed on range.